

# **Current Status of Interferometer Alignment**

K. Izumi for commissioning teams  
2018 Feb. 6th

# Status summary

## ✓ Interferometer beam: good

=> With the use of the optical lever, one can recover the alignment in a short length of time all the way back to BS.

## ✓ Baffle PD at EYC: OK

=> Two out of four were confirmed to be functioning.

=> The interferometer beam is occulted for the two non-responding PDs?

## ✓ ETMY rubbing issue: tolerable


=> Moving IPs somehow alleviated the issue.

## ✓ REFL port alignment: not yet done

=> Needs to commission the ETMY damping control loops.

# Baffle PDs

no response  
to the  
interferometer  
beam




good!!

**Note: all the PDs were tested in air and determined to be functional**

# PDs A and D are occulted?

It looks like this black aperture occults the beam.



# Rubbing issue

✓ **As we move the BF yaw picomotor, the horizontal LVDTs changed their DC positions.**

=> This sounds more like something below (e.g., the payload) was rubbing.

=> Ideally, the DC positions must not change.


=> This was corss-checked by moving the same picomotor for ETM\*X\* which didn't show a shift in the DC position.

✓ **The BF yaw transfer function was corrupted.**

=> In particular, the DC stiffness increased a lot, making the DC level lower by more than a factor of ten.


# Corrupted TF

Jan.13th  
good



Feb. 2nd  
bad

# After restoring the IPs



Much better although it seems still rubbing somewhere.

# Conclusions

- **Something was touching somewhere.**
- **Our best guess is that something below the BF stage was making the torsion degree of freedom stiffer by some means.**
- **The stiffness was found to be a function of the IP position and also the BF rotation angle (that controlled by the picomotor).**
- **The rubbing point is not yet identified.**



# Other concerns

- **The H1 and V2 LVDTs on BF don't show reasonable responses.**
  - => should be fixed from the outside of the chambers.**
  - => confusing when diagnosing the rubbing issue.**
- **Commissioning the ETMY damping loops is still under process. No real progress in this past week or two.**
  - => needs to be done before the REFL alignment.**
- **A type-A suspension has so many channels to investigate and makes diagnostic tasks very hard.**
  - => Needs some help from detchar e.g., summary page.**

# Review of the week starting Jan.31st

- ✓ Jan. 31st: Interferometer beam found at ETMs X and Y and BS. The EYA gate valve was found to be closed (4065).
- ✓ Jan. 31st: VIS team tried to release the support jack at EYV with no success (4066).
  
- ✓ Feb. 1st: The EY BF glitches were studied— they show up when there are constant DAC outputs. No idea why (4072).
- ✓ Feb. 1st: The interferometer beam was aligned again with the EYA gate valve open. Strange patterns were found on the ETMY mirror (4074).
- ✓ Feb. 1st: The baffle PD test was performed. Two out of four PDs are confirmed to be functional. Good enough (4085).
- ✓ Feb. 1st: optical lever spectra were found not to show the torsion peak at 20-30 mHz (4086).
  
- ✓ Feb. 2nd: BF yaw transfer function was found to be bad (4101).
- ✓ Feb. 3rd-4th: some remote measurements to assess the ETMY situation (4102-4107). The peak disappeared on 17th of Jan.
- ✓
- ✓ Feb. 5th: The ETMY IPs were pushed back to their original positions with a bit of success (4111).