


Seismic Vibration at Y-End

2015.01.10

Measured by Seismometer CMG-3T




inside concrete cut

Seismic Vibration at Y-End

2015.01.10

Measured by Seismometer CMG-3T




inside concrete cut

Seismic Vibration at Y-End

2015.01.10

Measured by Seismometer CMG-3T




inside concrete cut

Seismic Vibration at Y-End

2015.01.10

Measured by Seismometer CMG-3T




inside concrete cut

Seismic Vibration at Y-End

2015.01.10

Measured by Seismometer CMG-3T




inside concrete cut

Seismic Vibration at Y-End

2015.01.10

Measured by Seismometer CMG-3T



inside concrete cut